



Mr Raja gopalam

# WORKSHOP TECHNOLOGY

## PART III

BY

W. A. J. CHAPMAN

PH.D., M.Sc.(ENG.), M.I.MECH.E., M.I.PROD.E.

PRINCIPAL, HATFIELD TECHNICAL COLLEGE, HERTFORDSHIRE



THE ENGLISH LANGUAGE BOOK SOCIETY

*and*

EDWARD ARNOLD (PUBLISHERS) LTD.

# CONTENTS

	PAGE
<b>CHAPTER 1. MATERIALS — TESTING — FURTHER TREATMENT AND PROPERTIES.</b>	
Forms of Supply—Specification—Tensile Test—Proof Stress—Hardness Testing—Impact Test—Bend Tests—Erichsen Test—Work-Hardening—Grain Growth—High Speed Steel—Hardening—Salt Bath Furnaces—Gas Carburising—Nitrogen Hardening—Carbo-nitriding—Cyanide Hardening—High-frequency Heating—Flame Hardening—Gas Preparation—Hardening Instability and Faults—Mass Effects—Alloy Steels—Effect of Alloying Elements—Developments in Non-ferrous Metals . . . . .	1
<b>CHAPTER 2. PRIMARY AND CONTRIBUTORY PROCESSES.</b>	
Oxy-acetylene Welding—The Blowpipe—The Flame—High and Low Pressure Systems—Welding Practice—Butt Joints—Fillet Welding—Cast Iron Welding—Electric Arc Welding—Equipment—Practice—Surfacing—Stelliting—Carbon Arc—Argon Arc—Atomic Hydrogen—Submerged Arc—Stud Welding—Butt, Seam, Spot Welding—Gas Cutting—Horizontal Forging Machine—Forging Practice—Examples—Materials for Forging Tools—Cold Heading—Investment Casting—Shell Moulding—Lost Wax Process—Die Casting—Casting Alloys—Gravity Casting—Pressure Casting—Characteristics of Die Castings . . . . .	48
<b>CHAPTER 3. CONTRIBUTORY PROCESSES.</b>	
Presswork—Flypress—Foot-press—Power Press—Press Capacity—Blanking and Piercing—Press Tools—Blanking Layout—Multiple Blanking—Blanking and Piercing—Blanking Pressure—Bending—Allowance—Tools—Drawing Blank Size—Pressure Pads—Combination Tools—Coining and Forming—Hot Brass Pressing—Plastics Classification—Raw Material for Plastic Moulding—Compression Moulding—Presses—Platens—Moulds—Positive—Semi-Positive—Open Flash—Transfer—Die Metals—Die Hobbing—Sintered Metal Components—Production . . . . .	91
<b>CHAPTER 4. METAL CUTTING.</b>	
Cutting Action—Chip Formation—Built-up-edge—Mechanics of Cutting—Ernst and Merchant Theory—Lee and Shaffer Theory—Machineability—Tool Failure—Hot Hardness—Cutting Temperature—Influence of Microstructure on Cutting—Cutting Fluids—Tool Life—Sintered Carbides—Preparation—Properties—Carbide Tools—Use of Carbides—Chip Breaking—Negative Rake Cutting—Diamond Turning—Ceramic Tools—Electro-Erosion Machining—Spark Machining—Ultrasonic Machining—Surface Finish—Surface Characteristics—Microscopic Examination—Mechanical Examination—Measure Surface of Finish—Surface Nomenclature . . . . .	136

